

Switching diagrams 61001 – 61044

<p>61001</p>	<p>61002</p>	<p>61003</p>	<p>61004</p>	<p>61005</p>
<p>61006</p>	<p>61007</p>	<p>61008</p>	<p>61009</p>	
<p>61010</p>	<p>61011</p>	<p>61012</p>		
<p>61025</p>	<p>61026</p>	<p>61027</p>	<p>61028</p>	
<p>61029</p>	<p>61030</p>	<p>61031</p>		
<p>61032</p>	<p>61037</p>	<p>61038</p>	<p>61039</p>	
<p>61040</p>	<p>61041</p>	<p>61042</p>		
<p>61043</p>	<p>61044</p>			

Switching diagrams 61045–61062

61045

FA 6002	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36
1	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
2		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X

61046

FA 6002	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36	38	40
1	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
2		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X

61047

FA 6002	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36	38	40	42	44
1	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
2		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X

61048

FA 6002	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36	38	40	42	44	46	48
1	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
2		X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X

61049

FA 6005	2	4	6
1	X		
2		X	
3			X

61050

FA 6006	2	4	6	8
1	X			
2		X		
3			X	
4				X

61051

FA 6007	2	4	6	8	10
1	X				
2		X			
3			X		
4				X	
5					X

61052

FA 6008	2	4	6	8	10	12
1	X					
2		X				
3			X			
4				X		
5					X	
6						X

61053

FA 3015	2	4	6	8	10	12	14
1	X						
2		X					
3			X				
4				X			
5					X		
6						X	
7							X

61054

FA 3016	2	4	6	8	10	12	14	16
1	X							
2		X						
3			X					
4				X				
5					X			
6						X		
7							X	
8								X

61055

FA 3017	2	4	6	8	10	12	14	16	18
1	X								
2		X							
3			X						
4				X					
5					X				
6						X			
7							X		
8								X	
9									X

61056

FA 3018	2	4	6	8	10	12	14	16	18	20
1	X									
2		X								
3			X							
4				X						
5					X					
6						X				
7							X			
8								X		
9									X	
10										X

61057

FA 3019	2	4	6	8	10	12	14	16	18	20	22
1	X										
2		X									
3			X								
4				X							
5					X						
6						X					
7							X				
8								X			
9									X		
10										X	
11											X

61058

FA 3020	2	4	6	8	10	12	14	16	18	20	22	24
1	X											
2		X										
3			X									
4				X								
5					X							
6						X						
7							X					
8								X				
9									X			
10										X		
11											X	
12												X

61059

FA 6020	2	4
0		
1	X	
2		X

61060

FA 6021	2	4	6
0			
1	X		
2		X	
3			X

61061

FA 6022	2	4	6	8
0				
1	X			
2		X		
3			X	
4				X

61062

FA 6023	2	4	6	8	10
0					
1	X				
2		X			
3			X		
4				X	
5					X

Switching diagrams 61063–61082

61063

FA 3008	2	4	6	8	10	12
0						
1	X					
2		X				
3			X			
4				X		
5					X	
6						X

61064

FA 3009	2	4	6	8	10	12	14
0							
1	X						
2		X					
3			X				
4				X			
5					X		
6						X	
7							X

61065

FA 3010	2	4	6	8	10	12	14	16
0								
1	X							
2		X						
3			X					
4				X				
5					X			
6						X		
7							X	
8								X

61066

FA 3011	2	4	6	8	10	12	14	16	18
0									
1	X								
2		X							
3			X						
4				X					
5					X				
6						X			
7							X		
8								X	
9									X

61067

FA 3012	2	4	6	8	10	12	14	16	18	20
0										
1	X									
2		X								
3			X							
4				X						
5					X					
6						X				
7							X			
8								X		
9									X	
10										X

61068

FA 3013	2	4	6	8	10	12	14	16	18	20	22
0											
1	X										
2		X									
3			X								
4				X							
5					X						
6						X					
7							X				
8								X			
9									X		
10										X	
11											X

61069

FA 6005	2	4	6	8	10	12
0						
1	X					
2		X				
3			X			

61070

FA 6006	2	4	6	8	10	12	14	16
1	X							
2		X						
3			X					
4				X				

61071

FA 6007	2	4	6	8	10	12	14	16	18	20
1	X									
2		X								
3			X							
4				X						
5					X					

61072

FA 6008	2	4	6	8	10	12	14	16	18	20	22	24
1	X											
2		X										
3			X									
4				X								
5					X							
6						X						

61073

FA 3015	2	4	6	8	10	12	14	16	18	20	22	24	26	28
1	X													
2		X												
3			X											
4				X										
5					X									
6						X								
7							X							

61074

FA 3016	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32
1	X															
2		X														
3			X													
4				X												
5					X											
6						X										
7							X									
8								X								

61079

FA 6020	2	4	6	8
0				
1	X			
2		X		

61080

FA 6021	2	4	6	8	10	12
0						
1	X					
2		X				
3			X			

61081

FA 6022	2	4	6	8	10	12	14	16
0								
1	X							
2		X						
3			X					
4				X				

61082

FA 6023	2	4	6	8	10	12	14	16	18	20
0										
1	X									
2		X								
3			X							
4				X						
5					X					

Switching diagrams 61083–61111

61083

FA 3008	2	4	6	8	10	12	14	16	18	20	22	24
0												
1	X							X				
2		X							X			
3			X							X		
4				X							X	
5					X							X
6						X						X

61084

FA 3009	2	4	6	8	10	12	14	16	18	20	22	24	26	28
0														
1	X								X					
2		X								X				
3			X								X			
4				X								X		
5					X								X	
6						X								X
7							X							X

61089

FA 6005	2	4	6	8	10	12	14	16	18
0									
1	X				X			X	
2		X				X			X
3			X				X		

61090

FA 6006	2	4	6	8	10	12	14	16	18	20	22	24
1	X								X			
2		X								X		
3			X								X	
4				X								X

61091

FA 6007	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30
1	X									X					
2		X									X				
3			X									X			
4				X									X		
5					X									X	

61092

FA 6008	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36	
1	X												X						
2		X												X					
3			X												X				
4				X												X			
5					X												X		
6						X												X	

61093

FA 3015	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36	38	40	42	
1	X														X							
2		X														X						
3			X														X					
4				X														X				
5					X														X			
6						X														X		
7							X														X	

61094

FA 3016	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36	38	40	42	44	46	48
1	X																X							
2		X																X						
3			X																X					
4				X																X				
5					X																X			
6						X																X		
7							X																X	
8								X																X

61099

FA 6020	2	4	6	8	10	12
0						
1	X					
2		X				

61100

FA 6021	2	4	6	8	10	12	14	16	18
0									
1	X								
2		X							
3			X						

61101

FA 6022	2	4	6	8	10	12	14	16	18	20	22	24
0												
1	X									X		
2		X									X	
3			X									X
4				X								

61102

FA 6023	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30
0															
1	X														
2		X													
3			X												
4				X											
5					X										

61103

FA 3008	2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	32	34	36	
0																			
1	X																		
2		X																	
3			X																
4				X															
5					X														
6						X													

61109

FA 6020	2	4
0		
1	X	
2		X





















61110

FA 6021	2	4	6
0			
1	X		
2		X	
3			X

































61111

FA 6020	2	4	6	8	10	12
0						
1	X					
2		X				

























Switching diagrams 61112–61137



Switching diagrams 61151–61215



Switching diagrams 61217–61313



Switching diagrams 61314–61330

61314

FA 3113	2	4	8	10	X
L1L2		X			
L2L3			X	X	
L3L1	X				
L1N	X	X	X		
L2N		X	X		
L3N	X			X	

61317

FA 3111	2	4	6	10	X
L3L1	X				
L2L3		X			
L1L2	X		X		
0					
L1N	X	X			

61318

FA 3115	2	4	8	10	14	16	X
L3L1							
1 L2L3	X						
L1L2		X					
0							
2 L1L2	X						
L2L3		X					
L3L1	X						

61319

FA 3106	2	4	6	X
L1L2	X			
L2L3	X	X		
L3L1	X			

61321

FA 9078	2	4	X
L1L2	X		
0			
L1N	X	X	

61325

FA 9010	2	4	8	X
0				
1	X			
2	X	X	X	
3	X	X	X	

61326

FA 9015	2	6	10	14	X
1	X	X	X	X	
2	X	X	X	X	
3	X	X	X	X	
4	X	X	X	X	

61327

FA 9006	2	4	8	12	X
1	X	X	X	X	
0					
2	X	X	X	X	

61328

FA 9010	2	8	14	16	X
0	X				
1	X	X	X	X	
2	X	X	X	X	
3	X	X	X	X	






















61329

FA 9013	2	8	14	16	X
1	X	X	X	X	
2	X	X	X	X	
3	X	X	X	X	
































61330

FA 9015	2	10	12	14	22	24	X
1	X	X	X	X	X	X	
2	X	X	X	X	X	X	
3	X	X	X	X	X	X	
4	X	X	X	X	X	X	

Switching diagrams 61331 – 61485



Switching diagrams 61625–61917



Switching diagrams 61918–61932

